




— Cu = 1.0 - 1.5
 — Cu = 1.5 - 2.0
 — Cu > 2.0

VERTIKALPROFIL
 B2 = 11

1:500

1 4/1 0/85

GRONG GRUBER A/S

13003