




11098

nordre Knutshö

Situationsskizze
VAARSTIGEN

Tegn:

- stoll
- skjæring
- w røsk
- /// rustzone
- o borhol
- utmaalspkt.

Nov. 1937
E. Küll

1:10000