

11.1.

Mittre Vinoren


M = 1:250

Därlig gj. L = 72-m.






Defekt gj. L = 95.0 m

Gj. inntakt L = 29.3 m.

Gj. L = 29-m.



Gj. L = 31-m



14394

Kongsberg, den 5/2-78.
R. Kongsgård