



11. 1. Mittre Vinoren

M=1:250





Defekt gj. L = Ca. 80 m.




Gj. L = 25.- m.


Defekt gj. L = 23 m.




Defekt gj. L = 22.- m.




Gj. L = 32.- m.




Defekt gj. L = 45,5 m.




Defekt gj. L = 46.- m.



Gj. L = 29,5 m.



Defekt gj. L = 36 m



Kongsberg, den 5/2-78.
R. Kongsjord